



View of uncoated concrete manhole. Note the severe surface deterioration caused from exposure to sewage gas.



After abrasive blasting, manhole surface exhibits a very irregular substrate with exposed aggregate that would normally be smoothed with cementitious grouts or hand applied epoxy composites.

EF-1988 applied to manhole utilizing ECOSYSTEM<sup>®</sup> expansion technology. Surface preparation consisted of abrasive blasting only with no cementitious grouts or epoxies being applied prior to sprayout.

**Global EcoTechnologies, Inc.**  
315 Harbor Street  
Pittsburg, CA 94565  
Telephone (510)473-9250

