



View of uncoated concrete manhole. Note the severe surface deterioration caused from exposure to sewage gas.



After abrasive blasting, manhole surface exhibits a very irregular substrate with exposed aggregate that would normally be smoothed with cementitious grouts or hand applied epoxy composites.

EF-1988 applied to manhole utilizing ECOSYSTEM[®] expansion technology. Surface preparation consisted of abrasive blasting only with no cementitious grouts or epoxies being applied prior to sprayout.

Global EcoTechnologies, Inc.
315 Harbor Street
Pittsburg, CA 94565
Telephone (510)473-9250

